



MICHAEL R. STYLER Executive Director

JOHN R. BAZA Division Director

Inspection Report Minerals Regulatory Program Report Date: September 29, 2006



Mine Name: Windy 3

Operator Name: Color Country Rock

Preston Hafen 115 South Main Veyo, Utah 84782

Inspector(s): Doug Jensen

Permit number: S/053/071 Date: September 13, 2006 Time: 12:10 PM

Other Participants: None Mine Status: Inactive Weather: Clear, Warm Enforcement **Elements of Inspection** Evaluated Comment 1. Permits, Revisions, Transfer, Bonds 2. Public Safety (shafts, adits, trash, signs, highwalls) 3. Protection of Drainages / Erosion Control 4. Deleterious Material 5. Roads (maintenance, surfacing, dust control, safety) 6. Concurrent Reclamation 7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes) 8. Water Impoundments 9. Soils 10. Revegetation 11. Air Quality 12. Other Purpose of Inspection: Check the site while in the area **Directions to Site:** See previous inspection memo. **Inspection Summary:** The site appears to be unchanged since my last visit to the site on March 2, 2006. Conclusions and Recommendations: I will continue to monitor the site when I am in the area. ___ Date: _9/28/06 Inspector's Signature dj:pb Color Country Rock cc:

Russ Schreiner, BLM, St George FO UTU-79710 O:\M053-Washington\S0530071-Windy\Inspections\09132006insp.doc